




Starfire 2100C Operation

Iron plate cutting operation

1、Reset operation

Open Starfire ---F2 -----F3-----F7-----ESC。






2. Move the torch head(cutting head)

Press F2 ---Move ↑ ↓ ←→ to make the cutting head above the plate -----Adjust the cutting





head (Make the cutting head 3~4mm away from the metal plate.)





2、Select graphics

Press F6 Graphics Library to operate ----- Select the graphic you want to cut in F1 or F2 graphics library ----- You can change the size of the cutting graphic in the upper right corner of the screen (Note: Unit For mm)-----after change size and press F6 to submit ----- Press F7 to confirm.









3. Parameter adjustment

Press ESC to return to the main interface ----- Press F1 to operate automatically ----- Press F (yellow, in the upper right corner) to adjust the cutting speed. The cutting speed is generally set according to the thickness of the cutting plate -- ----- Press F5 to adjust the cutting gap.。






4. confirm the cutting graphics

Press F4 graphics operation to view the cutting graphics, confirm that there is no error ----- then press F4 graphics to operate back to the previous interface



5. Start cutting: Press Green button to start cutting.



Tube cutting operation

Ensure that the rotating shaft is completely parallel to the machine.



1. After fixing the tube, measure the circumference of the tube: $\text{Circumference length} = 3.14 * \text{Diameters}$




2. Reset operation

F2 -----F3 -----F7 -----ESC











3、Moving torch

Open the tube sheet cutting button ----- move the torch to the center of the tube cutting by operating the " ↑ ↓ ← → " buttons ----- adjust the height adjuster to the torch head Drop touches the tube ----- mark the torch touch point with a pen (either press the arc button or press the punch button to print the mark)












4. The X and Y coordinates are cleared. Write down the X-axis coordinate value of one rotation
 Press ESC to return to the main interface ----- press F2 manual operation ----- press F6 to clear the coordinate operation ----- press F2 jog operation to set the jog parameter (diameter *3.14)-----Press Enter to confirm the operation-----Press F (yellow, in the upper right corner) to adjust the cutting speed. The cutting speed is generally set according to the thickness of the cutting plate (2300- 2500 section)----- Press X (yellow, upper right corner) to make the machine enter the dry running state----- Press the green start button to let the machine rotate the axis to run empty, then observe the rotation Whether the point marked on the axis returns to the original position after one rotation (ie, the position of the marker point at which the torch head is aligned) There are two situations: first, if you can return to the original position, the calculated circumference value is correct; 2. If there is a deviation indicating that the measurement circumference is wrong, it is necessary to re-measure the circumference-----the measurement is correct and the X-axis coordinate value is recorded at this



time.







5, adjust the **X-axis pulse equivalent**


Press ESC to return to the main interface ----- Press F4 parameter operation ----- Press F2 system operation ----- Record the current pulse equivalent of the X axis (the value at this time is the plane cut value 0.003328) Ignore the Y



axis



X-axis pulse equivalent




6, calculate and adjust the X-axis pulse equivalent

Formula: Adjust X-axis pulse equivalent = Circle circumference (diameter * 3.14) / Round tube rotation X-axis coordinate value * X-axis current pulse equivalent (0.003328)

7. Set the X-axis pulse value


Calculate the value of the adjusted X-axis pulse ----- Enter the value of the X-axis pulse (other values are unchanged) ----- After changing, press F7 to save the operation ----- Press ESC to return to the main interface







8. Start cutting tube


Press F6 graphics library operation ----- Press F1 or F2 graphics library to select the cutting graphics --- adjust the cutting size in the upper right corner ----- press F6 to submit the operation -- -----Press F7 to confirm ----- Press ESC to return to the main interface ----- Press F1 to operate automatically ----- Press the green start button















9 After the cutting is completed, press ESC to return to the main interface, and change the X-axis value of the original system pulse equivalent parameter to 0.003328 (because the pulse equivalent of the plane cutting is different from the pulse equivalent of the round tube cutting)

uneedcnc